



My Team - Maintenance Report

Maintenance Service Report

Report ID: FF-1BACE866

Generated: 06/03/2026

JOB SUMMARY

The left hydraulic line on press #3 was replaced today, and the leak has been resolved. The equipment is currently operational. It is recommended to schedule the replacement of the right hydraulic line at the next maintenance visit.

JOB INFORMATION

Work Order	-
Asset	-
Location	-
Priority	-
Technician	-
Workspace	My Team
Generated	06/03/2026

ISSUE IDENTIFIED

Leak in the left hydraulic line on press #3.

CORRECTIVE ACTION

Replaced the left hydraulic line and performed a retorque. Conducted a 10-cycle test, confirming that the leak has stopped.

VERIFICATION PERFORMED

No leakage observed during the 10-cycle test.


EQUIPMENT STATUS

Operational.

RECOMMENDATIONS

It is recommended to replace the right hydraulic line during the next planned maintenance.

PHOTO DOCUMENTATION



Condition prior to repair



Condition after repair

TECHNICIAN REVIEW

☒ Report reviewed by technician

Technician: -

Date: 06/03/2026

ORIGINAL FIELD NOTES

Changed left hydraulic line on press #3. Leak stopped after retorque. Ran 10-cycle test - no drip. Recommend replace right line at next PM.